RANCHO CUCAMONGA

INSPECTIONS ROUTE ORDER (Group by: Assigned Inspectors)

Route Order 1 = 8am - 11am
Route Order 2 = 10am- 2pm
Route Order 3 = 1pm - 4pm

Alan

RECORD ID	INSPECTION TYPE	ROUTE ORDER	DATE SCHEDULED
PMT2024-02096	Foundation, Footing, Setbacks	1	11/5/2026
PMT2024-02122	Foundation, Footing, Setbacks	1	11/5/2026
PMT2024-02797	Combination	1	11/5/2026
PMT2024-04021	Pool- Excavation, Setbacks, Reinforcement, Bonding	1	11/5/2026
PMT2026-05127	Roof Sheathing, Nailing	2	11/5/2026
PMT2026-05017	Final Inspection	2	11/5/2026
PMT2026-04814	Electrical Utility Clearance (Edison)	2	11/5/2026
PMT2026-04814	Final Inspection	2	11/5/2026
PMT2026-04727	Pre-Inspection	2	11/5/2026
PMT2025-00105	Foundation, Footing, Setbacks	2	11/5/2026
PMT2025-00105	Underground, Drainage, Floor	2	11/5/2026
PMT2026-05120	Final Inspection	3	11/5/2026
PMT2025-01240	Wall Reinforcement, Rebar, Mid-Height	3	11/5/2026
PMT2024-05236	Electrical Utility Clearance (RCMU)	3	11/5/2026
PMT2025-05263	Final Inspection	3	11/5/2026

Ryan

RECORD ID	INSPECTION TYPE	ROUTE ORDER	DATE SCHEDULED
PMT2026-03395	Final Inspection	1	11/5/2026
PMT2026-04728	Excavation, Setbacks, Bonding (Pre-Gunite)	1	11/5/2026
PMT2026-04925	Final Inspection	1	11/5/2026
PMT2026-04482	Excavation, Setbacks, Bonding (Pre-Gunite)	2	11/5/2026
PMT2026-01662	Exterior Shear	2	11/5/2026
PMT2026-01662	Roof Sheathing, Nailing	2	11/5/2026
PMT2026-01667	Exterior Shear	2	11/5/2026
PMT2026-01667	Roof Sheathing, Nailing	2	11/5/2026
PMT2026-01671	Exterior Shear	2	11/5/2026
PMT2026-01671	Roof Sheathing, Nailing	2	11/5/2026
PMT2026-01674	Exterior Shear	2	11/5/2026
PMT2026-01674	Roof Sheathing, Nailing	2	11/5/2026
PMT2026-01676	Exterior Shear	2	11/5/2026
PMT2026-01676	Roof Sheathing, Nailing	2	11/5/2026
PMT2026-03232	Foundation, Footings, Setbacks	2	11/5/2026
PMT2026-03980	Final Inspection	2	11/5/2026
PMT2026-04448	Final Inspection	3	11/5/2026
PMT2026-05187	Final Inspection	3	11/5/2026
PMT2026-05014	Roof Sheathing, Nailing	3	11/5/2026
PMT2026-04511	Final Inspection	3	11/5/2026
PMT2026-03949	Final Inspection	3	11/5/2026
PMT2026-04400	Final Inspection	3	11/5/2026

Sebastian

RECORD ID	INSPECTION TYPE	ROUTE ORDER	DATE SCHEDULED
PMT2022-03097	Final Inspection	1	11/5/2026
PMT2023-00297	Final Inspection	1	11/5/2026
PMT2026-00385	Final Inspection	1	11/5/2026
PMT2026-03206	Foundation, Footings, Setbacks	1	11/5/2026
PMT2025-02663	Underground, Drainage, Floor	2	11/5/2026
PMT2025-00090	Rough Electrical	2	11/5/2026
PMT2026-02868	Foundation, Footing, Setbacks	2	11/5/2026
PMT2026-03300	Electrical Utility Clearance (Edison)	2	11/5/2026
PMT2026-03300	Final Inspection	2	11/5/2026
PMT2026-04405	Final Inspection	2	11/5/2026
PMT2026-01034	Rough Plumbing	2	11/5/2026
PMT2026-04857	Final Inspection	2	11/5/2026
PMT2026-04550	Final Inspection	2	11/5/2026
PMT2025-04460	Final Inspection	3	11/5/2026
PMT2026-05070	Final Inspection	3	11/5/2026
PMT2026-04802	Final Inspection	3	11/5/2026
PMT2026-05173	Electrical Utility Clearance (Edison)	3	11/5/2026
PMT2026-05173	Rough - Pre-Final	3	11/5/2026

Victor

RECORD ID	INSPECTION TYPE	ROUTE ORDER	DATE SCHEDULED
PMT2026-03594	Final Inspection	1	11/5/2026
PMT2026-02606	Final Inspection	1	11/5/2026
PMT2026-01052	Final Inspection	1	11/5/2026
PMT2026-01327	Final Inspection	1	11/5/2026
PMT2026-04114	Foundation, Footing, Setbacks	2	11/5/2026
PMT2026-04115	Foundation, Footing, Setbacks	2	11/5/2026
PMT2026-04116	Foundation, Footing, Setbacks	2	11/5/2026
PMT2026-02175	UFER	2	11/5/2026
PMT2025-04277	Final Inspection	2	11/5/2026
PMT2022-00775	Combination	2	11/5/2026
PMT2026-04104	Final Inspection	2	11/5/2026
PMT2026-05107	Rough Electrical	2	11/5/2026
PMT2026-02043	Foundation, Footing, Setbacks	2	11/5/2026
PMT2026-04828	Combination	2	11/5/2026
PMT2025-01275	Final Inspection	3	11/5/2026
PMT2026-04931	Final Inspection	3	11/5/2026